

#whdentalwerk  
     
 video.wh.com

Now at  
 your dealer  
 or [wh.com](http://wh.com)



# DIY-Service

## Alegra Spare Parts

In addition to the W&H Service you also have the opportunity to maintain your Alegra turbines and contra-angle handpieces yourself and to carry out minor repairs quickly and professionally on-site. Regular on-site maintenance extends the service life of your turbines and contra-angle handpieces and reduces downtimes.

### Do it yourself


Take a look at our Alegra spare parts overview and follow our video tutorials on our W&H Video Channel.



**alegra**



**Coupling seal**  
**BC**  
 REF 01000700  
**RM**  
 REF 02207300



**Short nozzle cleaner**  
 for turbine, contra-angle  
 and straight handpieces  
 REF 02015101



**Rotor with hexagon wrench**  
 for TE-98 LQ, TE-98,  
**TE-98 BC, TE-98 RM**  
 REF 06787500  
 for TE-97 LQ, TE-97,  
**TE-97 BC, TE-97 RM**  
 REF 07234100  
 for TE-95 RM  
 REF 07495400




**Water filter with resuction stop**  
 for BC connections  
 REF 07092500  
 for RM connections  
 REF 07095500



**O-ring set**  
 for Roto Quick couplings  
 REF 07508900



**Torque wrench**  
 for replacing the rotor  
 REF 07508800



**Tool kit for replacing**  
 of contra-angle heads  
 REF 07550300



**Generator**  
 for RQ-53  
 REF 06840300  
 for RQ-54  
 REF 06793000



**Push-button**  
 for TE-95 RM, TE-95 VC,  
**TE-98, TE-98 RM, TE-98 BC**  
 REF 06641900  
 for TE-97, TE-97 RM, TE-97 BC  
 REF 07548000



**Contra-angle head**  
 for WE-56  
 REF 07549900  
 for WE-57  
 REF 07550000  
 for WE-66  
 REF 07550100

### PLEASE NOTE!

**Tools:** For your own safety and the safety of your patients, please always order the compatible tools to carry out the repair in good quality.

**Original Spare parts:** The medical device loses its CE conformity if repairs are carried out with a non-original spare part. The use of non-original spare parts does not meet the high W&H quality standards. Safe use and a long product life can no longer be guaranteed.